


VM Machine in SDELAP02 can ping 10.100.13.21 but MPI gateway is not working and configuration from the web does not work



Configured for ISOTCP to MPI (Siemens S7-300/400)